

Technical Advice	
No.	TA 0201
Title	230V CCB Fuse Concern
Revision	01

Please note, we are aware of a concern where the T2A fuse on the Compressor Control Board (CCB) will blow.

This prevents the compressor from running, consequently the water will not cool.

To rectify this concern, we have tested and approved the use of a T3.15A fuse which can replace the T2A fuse on the CCB.